



INNER SOUND

ELECTRONIC SERVICE

1416 S.E. Morrison • Portland, OR 97214
(503) 238-1955 • FAX (503) 238-1787 • E-mail: inner@teleport.com

SHIPPING INFORMATION

We are the regional service center for many brands and the authorized service center for most brands.

For units covered by the manufacturer's warranty, we must have a copy of the bill of sale. This can be enclosed with the unit or faxed to us at the number above.

For units not covered by warranty, our estimate charge = our minimum labor charge (which is applied fully toward the repair):

- **\$50 for consumer units with 4 channels or less**
- **\$90 for 5.1 / 7.1 receivers, DVD-recorders, and anything with more than 4 channels**
- **\$90 for pro gear and reel-to-reels**
- **\$125 for most keyboards**

Please call or e-mail with any specific questions.

If you ship a unit to us for repair:

- **Complete the "Service Information Form". Enclose a copy with the unit. Keep a copy for your records.**
- **Package the unit VERY CAREFULLY. Insure it for full value.**
- **If the unit is not covered by warranty, enclose a check for the estimate charge or Visa/Mastercard information.**

Thank you.